

Summary of Action Items and Future Work
by Pat Cummins

WRAP Stationary Sources Joint Forum Meeting
June 2-3, 2003
Denver, CO

- 1) Complete project to identify BART eligible sources
- 2) Determine what work needs to be done to determine which of the eligible sources are subject to BART. How far down this path do we need to go if we are going to pursue an alternative approach?
- 3) Need input from state and tribal air managers on how to approach BART and/or alternatives.
- 4) BART work group will draft comments on BART proposal and forward to forum for review.
- 5) Use results of WRAP's causes of haze & attribution of haze projects to evaluate stationary source contributions to regional haze.
- 6) Ensure incorporation of tribal data.
- 7) Establish work group on oil and gas sources.
 - Work with WRAP Emissions Forum and states to collect data and prepare consistent base year (2002) emissions inventory.
 - Develop methods, including info from BLM, other federal agencies, and state agencies, to project 2018 inventory for oil and gas.
 - Begin scoping out potential strategies for reducing emissions (esp. NOx) from oil and gas sources
- 8) Need EPA guidance on whether a backstop approach, such as that used in the Annex, is acceptable under Section 308.
- 9) SO₂ - Evaluate options for expanding SO₂ annex to other states and tribes. Collect data on BART and non-BART SO₂ sources in non-Annex states.
- 10) SO₂ – In the event that utility SO₂ emissions in the West are covered under some future national program (legislation or regulation), what type of Western cap/sub-cap is appropriate (geographic coverage and level)?

11) NO_x -- Form work group and obtain contractor assistance to evaluate costs and emission reductions possible from electric utilities from application of combustions controls (build on EPA analysis and other work done by forum members).

12) What is universe of NO_x sources (BART and non-BART) other than utilities and oil and gas?

13) PM, VOC, NH₃ – What if anything is needed in next round of SIPs / TIPs to address stationary sources of these pollutants, including BART?